

Marstons Technical Service Advice and Guidance

Dispense System Hibernation

- 1. Disconnect kegs and casks and connect to the line cleaning system.
- 2. Chase out beer with fresh water.
- 3. Clean beer lines as you would do each week following recommended process and wearing PPE.
- 4. Once your line clean is complete leave fresh water in the beer lines.
- 5. Refresh the water every 7-10 days to ensure stagnant water does not contaminate
- 6. Switch off remote cooler and turn off gas systems at the bottles.

the beer lines.

In addition to the above – remove all spouts, creamer and sparklers from taps, wash them in hot water and leave to air dry in a safe place

Failure to follow the above process would result in irreversible contamination and unforeseen costs and damages